

# Procedure

## Lot Control and Traceability P7.5.3

### Rev. E

**Approved By:** Mike Orsini, Quality Manager

**Purpose:** To document procedure for lot control, traceability and inspection and test status.

**Scope:** All product requiring traceability. If customer requires different method we will follow their request.

**Authority:** The Plant Manager has the authority to change or modify this procedure.

#### Reference Documents and Records

- Policy Element 7.5.3 Identification and Traceability
- Quality Records Procedure P4.2.4

#### Change History

Date	Change	Rev	By
06/13/96	Modified paragraph 1. Removed & Start Project Planning form paragraph.	B	MO
12/10/96	Revised step 1 – added verbally notify Q.M. Revised responsibility column.	C	MO
02/09/99	Revised paragraph 3 to include the use of a manual method of recording and tracking customer lot numbers. Revise Paragraph 6 to show all personnel who could be responsible for generating the actual certification.	D	MO
10/21/2002	Updated procedure to ISO 9001:2000 Requirements to include inspection/test status and Flowcharted	E	MO

Lot Control and Traceability P7.5.3 Rev E.

